



DEPARTMENT OF
WATER RESOURCES

CENTRAL SACRAMENTO AREA *Fact Sheet* Site 71.7

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento River

River Mile: 71.7

Latitude/Longitude:

38.690894/-121.635491

Nearest Impact Area:

Woodland

County: Yolo

Bank: Right

Type of Damage

Bank erosion

Length of Repair

984 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources

**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

